




Circle Welders / Burners

Choose from the options below to fit your application

1 CIRCLE WELDERS




2 CARRIAGES



3 CENTERING DEVICES



4 CHUCKS



5 OPTIONS


Mechanical Oscillator
for use with CW-5 or CWE-5
CWO-1645

Mechanical Oscillator
for use with CW-7 or CWE-7
CWO-1645-7-50


Stand Alone Pend. Wvr.
for use with CW-5, CWE-5, CW-7
Digital Weaver

KEY
* = GMAW (Gas Metal Arc Welding) or GMAWP (Gas Metal Arc Welding Pulse) only
** = GMAW (Gas Metal Arc Welding), GMAWP (Gas Metal Arc Welding Pulse) and FCAW (Flux Cored Arc Welding)
*** = SAW (Submerged Arc Welding) only


1 CIRCLE BURNERS



2 MANIPULATOR MOUNTS



3 CARRIAGE MOUNTS



Ready to use as is